



Safe Work Procedure		Lawn Mower – Push (Gas)		
Department / Area: Physical Plant Services	Approved By: Regional Manager of Physical	Date Created: September 5 2014	Review Date:	
rnysicai riant services	Plant Services	September 5 2014		
			Revised date:	
Potential Hazards:		Personal protective equipment / devices		
Fill in those that apply H M L Risk for Injury		required / other safety considerations: Appropriate closed toe footwear		
Combustibles / flammables - gas		Eye Protection		
Rotating blades, debris thrown from blades		Hearing Protection		
Forceful exertions – thick grass, uneven terrain		Wear long pants		
□ ☑ □ Noise□ □ ☑ Surfaces causing falls – rough terrain		No electronic devices	when operating mower	
☐ ☐ ☑ Vibration – (hand, arm) increases effects with time		Training / Reference Information:		
□		Department Orientation		
☐ ☐ ☐ Awkward / sustained postures – forward lean		Operator's Manual		
Note: Signs and symptoms of a musculoskeletal injury (MSI) can include pain, burning, swelling, stiffness,				
numbness/tingling, and/or loss of movement or strength in a body part. Report these to your supervisor.				
Employers must ensure that workers are trained and follow this safe work procedure.				
Steps to perform this task safely:				
Ensure all shields and guards such as rear drag shield including discharge deflector are in place and working				
properly.				
 Avoid unnecessary engine idling in enclosed spaces such as sheds or garages. Avoid mowing areas close to where people are present. 				
 Block off areas, if necessary, with signage. 				
Make best efforts to clear the area to be mowed of any debris which could be thrown from the blades. Watch for				
hidden hazards such as holes, roots, drain pipes, or insect nests. Use caution around low hanging branches and				
shrubs.Only reach under the machine when it is turned off and the blades have stopped turning.				
 Do not touch hot motor parts or spray cold water on a hot engine. 				
Do not make wheel height adjustments, unclog chute, remove grass catcher, or refuel while the engine is running.				
Do not leave a running mower unattended.				
> Refuel in a well ventilated, level area and allow the engine to cool at least 10 minutes or as per operating manual				
prior to refueling.				
When leaving the machine:				
Disengage power to the	Disengage power to the blade.			
Stop the engine.				