

Team Name: Environmental	
Services	Reference Number: ORG.1910.PR.005
Team Lead: Regional Manager Environmental Services	Program Area: Support Services
Approved by: Executive Director - Acute & Chief Nursing Officer	Policy Section: Housekeeping
Issue Date: January 29, 2020	Subject: Cleaning and Appearance Standards, General Room Area
Review Date:	
Revision Date:	

Use of pre-printed documents: Users are to refer to the electronic version of this document located on the Southern Health-Santé Sud Health Provider Site to ensure the most current document is consulted.

PROCEDURE SUBJECT:

Cleaning and Appearance Standards, General Room Area

PROCEDURE:

- 1. Baseboards
 - Baseboards appear to be clean and free of soil.
 - Corners and tops of baseboards are free of dust, lint and soil.
 - No soil present from floor cleaning method (mopping, waxing and shampooing).
 - Baseboards and coving appear to be in good repair.

2. Blinds

- > Blinds are in proper position.
- Blinds appear to be clean and free of soil.
- Blinds are operable.

3. Ceiling

- Ceiling appears free of dust, cobwebs and soil film.
- Ceiling has a good appearance.
- Millwork (if present) free of dust and lint deposits.
- Ceiling is intact, no loose or missing tiles (if present).
- No cracks or holes which presents a safety hazard.

4. Chairs

- Chairs are properly placed.
- Chairs appear clean, free of stain and soil.
- > Side rails or base rungs are free of dust and lint.
- No evidence of food or debris at base or in cracks or seat.

No mop stands or soil on legs.

5. Couch

- > Couch properly placed.
- Couch appears clean and free of stain and soil.
- No evidence of food products or debris at base of cushion.
- > Arms, if wood, are polished.

6. Desk

- Desk unit is in proper position.
- Desk appears to be clean and free of soil.
- > Top, side and bottom free of dust and lint.
- If unit is of wood, polished with no streaks.
- Miscellaneous equipment, clear of dust (telephone, file basket, etc.).

7. Door/Ledges/Frame

- a) Door
 - Door appears to be clean.
 - Doors are free of finger marks and soil.
 - Push or kick plates clean and free of soil from mopping or floor finish.
 - Edges of the door are clean.
 - Hardware is clean.

b) Ledges

Ledges over door are free of dust and lint.

c) Frame

- Frame is free of soil build-up.
- > There are no smudges or finger marks present.

8. Drapes

- Drapes are properly hung and match.
- > Drapes are in proper position.
- Drapes appear to be clean.
- Drapes are in good repair and not torn or spotted.

9. Drape Tracks

- Tracks appear to be clean and free of soil and dust.
- Carrier guides and/or curtain hooks are operable.
- > Tracks are intact and present no safety hazard.
- No cobwebs present.

10. Floor

- a) Carpet
 - Carpeting appears clean, free of litter and soil marks.

- No badly torn or worn spots or crushed traffic lanes.
- Carpeting appears well maintained.

b) Flooring

- Floor has no build up of finish.
- There are no black marks, scratches or formation of traffic lanes.
- Floor is free of litter, dust and dirt.
- Floor appears clean, with a visible shine.

11. Light Fixtures

- Light fixtures appear clean and free of lint, dust and soil.
- Lights, if movable, are in proper position.
- > Fixtures and bulbs in operable condition.

12. Mirror

- Mirror in proper position.
- Mirror appears to be clean.
- No finger marks or smudges.
- Mirror is intact.

13. Pictures

- Picture hanging straight on wall.
- No dust or lint on frame.
- No finger marks or smudges on glass covering.

14. Radiators/Baseboard Heaters

- Radiators appear free of dust, lint or soil.
- There are no removable marks.

15. Vents

- Vent appears to be clean and free of dust or lint on outer surface.
- Inside of vent does not have build-up of dust or lint.
- No soil around vent facing.
- Securely fastened and not a safety hazard.

16. Waste Containers

- Waste containers are in proper place.
- Waste units appear to be clean and free of soil.
- Waste container appears to be in good condition.
- Plastic liner in place.

17. Window / Sills

- Glass and frame appears to be clean and free of dust and spots.
- No finger marks or smudges.
- Window sills are free of dust, marks and spots.

18. Walls

- > Appear clean with no marks and damage.
- No visible paint chips.